

INSURED/APPLICANT NAME HECTOR RODRIGUEZ APPLICATION / POLICY # \_\_\_\_\_  
 ADDRESS INSPECTED: 857 SW MCCOMB AVE, PORT ST LUCIE, FL 34953  
 ACTUAL YEAR BUILT: 1986 DATE INSPECTED: 09 JUN 16

**Minimum Photo Requirement:**

- ☐ Front elevation ☐ Rear elevation  
☐ Main Electrical Service Panel with interior door label  
☐ HVAC heating systems equipment (with dated manufacturer's plate)  
☐ ALL hazards or deficiencies noted in this report.

Melvrobinson@comcast.net  
772-708-1518

**A Florida-licensed inspector MUST complete, sign and date this form.**

**ELECTRICAL SYSTEM (\*SEPARATE DOCUMENTATION OF ANY ALUMINUM WIRING REMEDIATION MUST BE PROVIDED AND CERTIFIED BY A LICENSED ELECTRICIAN)**

<b>Main Panel:</b> Panel Age: <u>30 years</u> Year Last Updated: <u>Unknown</u> Amps: Less than 60A Fuse <input type="checkbox"/> 60A Fuse <input type="checkbox"/> 100A Fuse <input type="checkbox"/> 100A CB <input type="checkbox"/> 200A CB: <input checked="" type="checkbox"/> Other (specify): _____	<b>Panel #2 (if present):</b> Year Panel #2 added: <u>N/A</u> Purpose of Panel 2: _____ Amps: Less than 60A Fuse <input type="checkbox"/> 60A Fuse <input type="checkbox"/> 100A Fuse <input type="checkbox"/> 100A CB <input type="checkbox"/> 200A CB: <input type="checkbox"/> Other (specify): _____	Total System Amps: _____ <b>Wiring Type</b> Copper Wiring, NM, BX, Conduit: <input checked="" type="checkbox"/> Active Knob & Tube or cloth wiring: <input type="checkbox"/> Aluminum Branch Wiring*: <input checked="" type="checkbox"/> Other (specify): _____
<b>Hazards Present</b> Blowing Fuses or Breakers <input type="checkbox"/> Empty Breaker <input type="checkbox"/> Loose Wiring <input type="checkbox"/> Improper Grounding <input type="checkbox"/> Over Fusing <input type="checkbox"/> Double Taps <input type="checkbox"/> Exposed/Unsafe Wiring <input type="checkbox"/> Electrical Panel Brand/Model <u>Square D</u> Other (explain) _____	* If single strand (aluminum branch) wiring, provide details of all remediation. <i>Separate documentation of all work must be provided.</i> Entire home rewired with copper <input type="checkbox"/> Connections repaired via COPALUM® crimp <input type="checkbox"/> Connections repaired via AlumiConn® <input type="checkbox"/>	

Is the electrical system in good working order? ☒ Yes ☐ No (explain) \_\_\_\_\_

**Use the Additional Comments/Observations section below to provide full details of any noted updates, hazards, etc.**

**HEATING SYSTEM**

Age of System: <u>20 YEARS</u> Year Last Updated: <u>2006</u> Compressor _____ Are the heating, ventilation and air conditioning systems in good working order? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No (explain) _____	<b>Hazards Present</b> Wood Burning Stove or central gas fireplace not professionally installed? <u>N/A</u> <input type="checkbox"/> Yes <input type="checkbox"/> No Space heater used as primary heat source? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Central HVAC <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If not central, indicate <b>primary</b> heat source and fuel type: _____ Is the source portable? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	--	---

**Use the Additional Comments/Observations section below to provide full details of any noted updates, hazards, etc.**

**PLUMBING SYSTEM**

Age of System: 30 YEARS

Year Last Updated: 2008

Deficiencies (check all that apply):

Type of Pipes

Copper: ☒

PVC: ☒

Galvanized: ☐

Polybutylene: ☐

Other (specify): \_\_\_\_\_

Water heater

Is the plumbing system in good working order?

☒ Yes ☐ No

Active leak ☐

Indication of prior leak(s) ☐

Connections/Hoses leaking or cracked ☐

Water Heater (explain) ☐

Other (explain) ☐

*Use the Additional Comments/Observations section below to provide full details of any noted updates, hazards, deficiencies, etc.*

**ROOF - WITH 2 ROOF PHOTOS, THIS PORTION CAN TAKE THE PLACE OF THE ROOF CONDITION CERTIFICATION FORM (CIT RCF-1)**

**Predominant Roof**

Fiberglass

Covering Material: Shingle

Roof Age (years): 12 YEARS

Remaining Useful Life: 8 YEARS

Date of Last Roofing Permit: 2004

Date of Last Update: 2004

*If updated (check one):*

Full Replacement ☒

Partial Replacement ☐

% of Replacement \_\_\_\_\_

*Overall Condition of Roof:*

Excellent ☐

Good ☒

Fair ☐

Poor (explain) ☐

**Secondary Roof**

Bitumen

Covering Material: Bitumen

Roof Age (years): 12 YEARS

Remaining Useful Life: 7 YEARS

Date of Last Roofing Permit: 2004

Date of Last Update: 2004

*If updated (check one):*

Full Replacement ☒

Partial Replacement ☐

% of Replacement \_\_\_\_\_

*Overall Condition of Roof:*

Excellent ☐

Good ☒

Fair ☐

Poor (explain) ☐

*Any visible signs of damage / deterioration? (describe) (e.g. curling/ lifted/ loose/ missing shingles or tiles, sagging or uneven roof deck)*

Predominant Roof

☐ Yes ☒ No

Secondary Roof

☐ Yes ☒ No

*Any visible signs of leaks?*

Predominant Roof

☐ Yes ☒ No

Secondary Roof

☐ Yes ☒ No

*Use the Additional Comments/Observations section below to provide full details of any noted updates, hazards, etc. for all roof coverings.*

**ADDITIONAL COMMENTS OR OBSERVATIONS (USE ADDITIONAL PAGES AS NEEDED):**

Observed two MULTI STRAND, not single strand aluminum circuits. Possible over heating of main at the panel. Consult with a licensed electrician and repair or replace as needed. Roof ridge vent is loose, missing a piece of ridge cap and minor damage to some shingles due to tree branches.

ALL 4-POINT INSPECTIONS MUST BE INSPECTED AND COMPLETED BY A VERIFIABLE FLORIDA-LICENSED INSPECTOR. I CERTIFY THAT THE ABOVE STATEMENTS ARE TRUE AND CORRECT.

*Jon P. LeVasseur*

St Cert Building Contractor CBC 059494

St Cert Home Inspector

HI 2667

09 JUN 16

INSPECTOR SIGNATURE

TITLE

LICENSE NUMBER

DATE

**A 4-Point Inspection is required for all homeowner, dwelling and mobile home applications for properties over 30 years old.**

The Citizens 4-Point Inspection form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection submitted for consideration must include at least this level of detail to be acceptable to Citizens.

**PHOTO REQUIREMENTS**

Photos must accompany each 4-Point inspection submitted to Citizens. The minimum photo requirement for all submissions is a front and rear elevation. However, there are additional photo requirements for a 4-Point inspection such as:

- Open Main Electrical Panel and Interior Door
- HVAC heating system (with dated manufacturer's plate)
- ALL hazards or deficiencies noted

**ROOF REQUIREMENTS**

The Citizens 4-Point inspection may be submitted in lieu of the Citizens Roof Condition Certification Form (CIT RCF-1) if a minimum of 2 photos of the roof are also provided. This will satisfy the required roof documentation listed in the Citizens Rules Manual.

**INSPECTOR REQUIREMENTS**

All inspection forms must be inspected and completed by a verifiable Florida-licensed professional. Without a verifiable, certified inspector's dated signature, the form will not be accepted. The following **FLORIDA-LICENSED** individuals may complete a 4-Point Inspection for Citizens in its entirety:

**Note:** A trade-specific, licensed professional may sign off only on their trade component of the 4-Point inspection form (e.g., a roofing inspector may sign off only on the roofing portion of the form).

- A general, residential, or building contractor
- A professional engineer
- A building code inspector
- A building code official who is authorized by the State of Florida to verify building code compliance
- A registered architect
- A home inspector

**CERTIFYING THE CONDITION OF EACH SYSTEM**

The Florida-licensed inspector is required to certify the condition of the electrical, HVAC and plumbing systems. "Acceptable Condition" means that each system is working as intended and there are no visible hazards or deficiencies.

**ADDITIONAL COMMENTS OR OBSERVATIONS**

This section of the 4-Point inspection must be completed with full details/descriptions if **any** of the following are noted on the inspection:

- Updates (provide full details of the types of updates, date completed and by whom)
- Any visible hazards/deficiencies are present
- Any system determined **NOT** to be in good working order.

**NOTE TO ALL AGENTS**

The writing agent must fully review each 4-Point inspection submitted with an application for coverage in advance. It is the agent's responsibility to ensure that all Citizens rules and requirements are met before the application is bound. Properties with electrical, heating or plumbing systems not in good working order **or** with existing hazards / deficiencies cannot be submitted to Citizens.






Front and left side elevation





Rear and right side elevation




Square D panel and exposed panel









Multi strand aluminum wiring circuits observed in panel



Electrical panel main ground and possible overheated main/oxidized




Data plate and HVAC air handler, located in the utility room, data plate hard to read but believe the unit is a 1996 unit.



Data plate & HVAC compressor





Water heater data plate and unit located in utility room



Washing machine and utility sink water shut off valves



Kitchen sink water supply shut off valves



Hall bathroom toilet and vanity water supply shut offs





Master bathroom toilet and vanity water supply line shut offs



Fiberglass shingle and bitumen roof media along with loose ridge vent



Missing ridge cap and shingle wear due to tree branches

